

SENSOR MEASUREMENT CONSOLE XA-M



FUNCTION

XA-m can read force or torque sensor values. Using the connector, auto recognition of the sensor sets up the console (force, pression, torque) and reads sensor's characteristics (calibration date, gain, ...)

LCD screen and only three buttons make an **intuitive and easy programmable interface**.

Small, robust and maintenance free, this console is simple and user-friendly device.



TECHNICAL INFORMATION

Measurement mode	Peak-hold or live display
Memory	Onboard memory 200 values – 15 recordable programs (min max threshold)
Sampling rate	1kHz average - 4 user selectable values
Connectivity	RS232 protocol
Accuracy	0.5% of full scale
Power	Battery with charger
Connectique	Port RS232
Language	English, French
Dimensions	w160xd115xh75 mm
Weight	800g
Guarantee	3 years

OPTIONS

Printer
PC RS232 cable or RS232-to-USB
DataXport® Software for data export on PC

● Provided with:

- Transport case
- Battery charger
- Calibration certificate for a given load cell

